

Appendix H Supplemental Photographs



Figure H 1. Brecciated boulder lodged into the back of the spa facility at TLR. Boulder is approximately 2 m tall and 3 m in length. Photograph taken November 13, 2016.



Figure H 2. Rockfall boulder with evidence of tectonic cataclasis that impacted the back of an equipment room at TLR. Photograph taken November 13, 2016.



Figure H 3. Close up view of tectonic cataclasis in rockfall boulder at TLR. Photograph taken November 13,2016.



Figure H 4. Composite image of failure west of TLR as shown in Figure 5-2(a) in main body of thesis. Created from photographs collected November 6, 2016 looking north-west.



Figure H 5. Composite image of failure west of TLR as shown in Figure 5-2(b) in main body of thesis. Created from photographs collected November 6, 2016 looking north-west.



Figure H 6. Composite image of failure west of TLR as shown in Figure 5-2(c) in main body of thesis. Created from photographs collected November 6, 2016 looking north.



Figure H 7. Composite image of failure above TLR as shown in Figure 5-2(d) in main body of thesis. Created from photographs collected November 6, 2016 looking north, north-east.



Figure H 8. Composite image of failures east of TLR as shown in Figure 5-2(e ,f) in main body of thesis. Created from photographs collected November 6, 2016 looking north-east.