Appendix B

Chief Historical Rockfalls




Figure B1: Key plan of identified rockfall scars on the North Wall of Stawamus Chief

Table B1: Images of identified rockfall scar point clouds and reconstructed blocks

Rockfall number	Scar Surface	Reconstructed Block
1	20 m	20 m
2	20 m	

